Mr. Steven W. Bolton innovative Developers-Investors, Inc. 500 West 13th Street Fort Worth, Texas 76102

ODD SINCLACK CONSOLIDATED OCC.

Re: Old Sinclair Size, TX8923 COLD CKHIND

Fort Worth, Texas

Dear Mr. Bolton:

700980795710

I have enclosed a copy of the inspection report for this site and reviewed the report. The inspectors did not find any problems when they inspected the site; however, we cannot guarantee that an unknown disposal area is not located at the site. The inspection turned up information that wastes may have been deposited on the surface around 1930 to 1948, but no evidence of environmental damage or contamination was found during the inspection.

During your core testing you could have samples analyzed by a laboratory for petroleum type components since the site was used by an oil refinery. I cannot recommend any specific lab, but the analysis, if you decide that it is necessary, should probably include aromatic hydrocarbons such as polynuclear aromatics, benzene, etc.

If you have any questions, please contact Larry Thomas at (214)767-9700. Sincerely,

Samuel L Nott, Chief Superfund Enforcement Section

Enclosure

6AW-SE:THOMAS:tdt:x4076:12-6-83:Disk #1:Doc #1

SUPERFUND FILE

JAN 1 8 1993

REORGANIZED

9140716

